

### King County International Airport

Department of Construction & Facilities Management P.O. Box 80245 Seattle, WA 98108 (206) 296-7380

## FAX TRANSMITTAL SHEET

(206) 296-0 (206) 296-0	100 TDD	DATE	E: 11-30-98
		NO. OF PAGES INCLUDING COVER	₹: 1
	NAME	COMPANY	FAX NUMBER:
TO:	Peter Hogan	TPS	206 938 1576
CC:	· ·	· · · · · · · · · · · · · · · · · · ·	
_			
FROM:	JEFF WINTER AIRPORT ENGINEER	PHONE: 206-296-7425	FAX: 206-296-7385
UBJECT:	NE T-Hangus	book	
on pe	e 1,1998. Luxe confirm A:	AP if this can hap	sen for tomorr
			/
		ORIGINAL TO FOLLOW IN MAIL	



# Tacoma,WA

## I S TECHNOLOGIES IT ...

Soil Recycling Facility	Soil Data and (	Certification Sheet	Date: _//-	) - 1 - 0					
GENERATOR: King Count	y Airport	CONSULTANT: _	Olympus Envi	conmental					
Mailing Address: PO Box 80	245	Address: 8647	5 2124 St						
Scattle WA 98	108	Kent	WA 98031						
Contact Jeff Winter		Contact: Jim	Bonten						
Phone: (206 ) 296 74	25	Phone: (2-53	1 735-662	5					
Fax: (206) 296 73	85	Fax: ( 253 )	395-1170						
SITE NAME: K.C. August -	NE T-Hansaus	TRANSPORTER:	Shear Trans	purt					
	retar Road 5	Address: 267	19 SR 410 E						
Scattle WA	98/08	Buckley WA 98321							
Contact: Same		Contact: But	L Eaton						
Phone: ()		Phone: (360	) 829 910C	)					
Fax: ( )		Fax: (360)	829 4123	)					
Site History									
Type of contamination (gas, diesel used oil) coal tar, etc) havy oil diesel Estimated quantity in tons: 500  How did soil contamination occur? whenown, discovered drying gootechnical borns									
How did soil contamination occur? _	unknown, dis	covered duri	ry geotechni	ial boring					
	last □ spill □ eme	DOENICY DESPONSE	☑ OTHER _unl	k					
Name of Testing Lab: Sound									
	<b>V</b> .								
How and where at site were samples take	ten! Thum og old	unpres en boy.	m voige water	> 9 1000					
Please check appropriate box below and discrete grab samples should be collecte less, seven samples for 1500 tons or less	ed with the following frequen	cy: Three samples for t	he first 150 tons; five sa	amples for 750 tons or					
I certify that the soil referenced herein is contaminated solely by virgin petroleum products from leaking underground storage tank(s).	I certify that some or a non-virgin petroleum production storage tank or spill.			n is used oil or some other om a leaking above-ground					
Attach analysis for the following:  1. Total petroleum hydrocarbons (WTPH-G, WTPH-D, 418-1)  2. Benzene/ toluene/ ethylbenzene/ xylene (Method 8020 BTEX for gasoline soils only)  3. Total lead (Method 6010, 7420, or	Attach analysis for the follow  1. Total petroleum hydrocart  2. Benzene/ toluene/ ethylb  3. Halogenated Volatile Orga  4. Pesticides and PCB's (Messent)  5. Total metals concentration	bons (WTPH-G, WTPH-I benzene/ xylene (Metho anics (Method 8010, 802 thod 8080)	d 8020 BTEX for gasolin 1, or \$240)  (a) arsenic (d) ch (b) barium (e) le	e soils only)*  nromium (g) selenium					
7421 for gasoline soils only)	* If elevated benzene and to and TCLP metals may be rec		are detected, additional a	nalyses for TCLP benzene					
No soils referenced herein may be assigns a delivery date. If any soils dwaste" pursuant to state regulations, acting as Client's agent, may arrange This is a complete and accurate de known or suspected hazards have bedefined by U.S. Environmental Prote concerning other TCLP constituents be required analysis reports are attached Generator/Owner Authorized Signature.	elivered to TPST are found to Client shall be solely respons for such removal at Client's escription of the soil reference on disclosed herein. I further ction Agency (EPA), State of nave been withheld. I further	be "hazardous waste" sible for their removal. I expense. ed herein; no deliberate r hereby certify that the of Washington, or local r certify that the soils re	pursuant to federal regular feat fails to so remore willful omissions has soil is not "hazardous" regulations, and that no	ulations or "dangerous love such soils, TPST, live been made and all or "dangerous" as to other knowledge a no free liquids. All					
Print Name: Jeffrey W.	, , ,		Invant Em in	Ser-					
rint Name: Oct 1 149	- V/ F F 1 - V		R R	evised 02/16/95					

# SOUND ANALYTICAL SERVICES, INC.

Summary of Results for Sound Analytical Ser\_ces Laboratory Number 77075

SAS Sample #	Client Sample	Date Received	Date Prepared	Ome Analyzed	Matrix	% Solids	Parameter	Result	POL	Flags	Units
	8195-1	11/16/98	11/19/98	11/21/98	5054	65.64	Diesal (>nC12-nC24)	71	<b>22</b>	X	May de
77875-01 8195	6(23-1	6(35-1 (11)-0-50	11113100				Matter Oil (>mC24-rrC32)	420	44		mpha
77677 66	010E 3	8195-2 11/19/98 11	11/19/98 17	11/21/98	soliti	83.02	Diesel (>nC12-nC24)	69	22	X	wayda
77075-02	9133-5			4 40E 1994			Maker Oil (>nC24-nC32)	420	- 44		mgikg
∿ <u>=====</u>		8195-3 11/19/98 1	(9) 11/(9/9B	11/19/66	selid	74.31.	Diesel (-nC12-nC24)	ND	25		mg#tg
77075-03 8195-3	5195-3						Motor Oil (>nC24-trC32)	ND ND	49		mgdkg
77075-04 8196		8196-4 11/16/08	11/19/20 11/19/	444000	bilec 80'02'	72.72	Diesel (>aC12-iC24)	ND	27		mg/kg
	8196-4						Motor Oil (>nC24-nC32)	130	53_		TOTAL
		4141000	11/19/96	11/20/98	solid	65.18	Diesel (>nC12-nC24)	160	110	XI	wâged
T7#75-05	6195-5	11/10/08		1120150	- anima		Motor Oil (>qC24-qC32)	1180	220		mgfkg
		4 4 4 5 4 5	11/19/98	11/21/98	selid	#4 21	Oiesel (>nC12-eC24)	110	24	<b>1</b> 00	mg/tg)
77075-05	8195-6	8195-6 11/16/98	11113430	1 (12 (130	-Co-Carine	-3.2.0	Motor Oil (>nC24 nC32)	510	47		mg/hg

XI = Chromatogram suggests this snight be beavy oil.

SEA402472

Erristing Bld.

Steam Man & 37

1

4 '98 g7; ZEAM KING COUNTY INTL.

NOT TO TCALL

ECIA
Soil Excavation
Sample Countron
w/ Results
il/24/68
Olympus Enumermentar

KCSlip4 35928

John Amico Ken Capo Flying Clab 8846 SE 59 Hh St Mercer Isl 98040